

degrees of freedom, ν

A statistical quantity indicating the number of values which could be arbitrarily assigned within the specification of a system of observations. For simple replication, with n measurements and one estimated parameter (the mean), $\nu = n - 1$.

More generally, for multivariable computations, the number of degrees of freedom equals the number of observations minus the number of fitted parameters.

1994, 66, 599