

**escape depth (for surface analysis techniques)**

The distance into the sample measured from the physical surface from which all but a fraction  $1/e$  of the particles or radiation detected have originated.

1979, 51, 2247